

~~Deck~~ Sheerstrake .50' instead of .36' as required.

"Tenedos."

It is submitted the Hull Surveyors be
informed that it is concluded the screw shaft
is fitted with a continuous & is $7\frac{5}{8}$ " diameter
as is fitted in sister vessels of the same class but
they should state whether this is so.

Clayton 28/10/19

RUD.

27/10/19

Lloyd's Register
Foundation

015026-015032-0042

27.10.19