

La correspondencia  
debe dirigirse a los  
Inspectores.



INSPECTORES:

CRAWFORD.

DE BERAZA.

C. KENDALL.

T. B. SCULLARD.

E.

# Lloyd's Register of Shipping.

OFICINA PRINCIPAL: FENCHURCH STREET, 71, LONDRES, E.C.3.

Calle de Ibañez de Bilbao No. 22,

4th Storey

(Apartado 286),

Bilbao, 1st April, 1931



Dear Sir,

With reference to your letter of the 25th ult., regarding our First Entry Report No. 7896 on the T.S.S. "CAMPOAMOR" we beg to inform you that in order to obtain a better disposition of the rivets in the longitudinal seams of the Donkey Boiler shell the pitch was slightly reduced. The rivet pitch of 185 mm. as reported, being the minimum pitch as drilled in the shell, was taken for calculation purposes, which gave strength of longitudinal joint, plate 84%, rivets 105%, combined 89.25%, and working pressure of shell by rules 198 lbs square inch.

The main stays are turned down to 60 mm. diameter in the body for a short distance clear of the thread in order to give a plus thread, the remainder of the body of the stays being full size.

We are, Dear Sir,

Yours faithfully

For the Surveyors

The Secretary  
LONDON.



© 1931

Lloyd's Register  
Foundation

015026-015038-0128



$x^4 \times x^7 = x^{11}$

1930 - March 5-6 April 10-11-15-15-18-24-25-29-30 May 3-5-7-8-10-12-16-17-17-20-22-22-24-28-29-30