

Do. of space or spaces }
between Tonnage Dk

SERVICES ON RIVER THAMES. Condition of Classy
Length from fore part of stem to after part of stern } L 70.00
most on summer T.W.T. See Sec. 2 (1a)

Launched 26th NOVEMBER

c.c. 4/3.

ssrs. W.J.Yarwoods & Sons, Northwich.

Yard No.886

Sister ship "ESSO GREENWICH"

Surveyors.....

Received from Chief Surveyors.....

NAME Motor Tug "ESSO READING" REPORT Liv. No. 139120

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~

cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

vey FIRST ENTRY ~~XXXXXX~~

L. 70.0'

B. 19.5'

D. 9.5'

The equipment supplied has been accepted for the Figure '1' in view of the restricted service of the tug.

Al "For River Thames Towing Services"

- ✓ "pt Elec. welded"
- ✓ FPT 1lt; APT 10t.
- ✓ FK, 4BH, Lloyds A & CP
- ✓ O.L. 75.8 + 75.6"
- ✓ Extreme breadth: 19.8' = 19'10"

Amend O.L & E.B in
R.B. / RSP 12/10/61.

24.2.54.



© 2021

Lloyd's Register
Foundation

Side Keelsons, No. each side.....

Fourth Deck, amidships, Angle, [or [.....