

ss. "T.W.1"

With regard to London Report No.126447 the recommendations contained therein were considered to be the minimum necessary to enable the ship to have class restricted to the Thames Estuary.

The recommendations detailed therein were communicated to the Owners for the above restricted service.

E. Luke

9.3.53.



© 2021

Lloyd's Register
Foundation

015155-015162-0011