

21 AUG 1954

P/S NAME "SOUTHGATE" REPORT Sou. No. 22465

standing Conditions of Class: Subject to permanent repairs to damaged bow plating (s.s.) next drydocking.

ACTION is DEFERRED for examination in dry dock and repairs after grounding by 31.6.54.

orsement of Class (B) (~~As before~~ or None)

ure of Present Survey: (~~Afloat and~~ in dry dock)

Docking: Damages (various).

ommendation:

SUBMITTED record of docking 7,54 be assigned, subject to indented shell plates E.3, 7, & 8 (p.s.) and E.8 (s.s.) and bulwark plating (p & s) being dealt with by next Special Survey, but without other condition.

7,54 Sou. Subject
Without.

~~DELETE FROM S.R.L.
Drydocking (grounding).~~



© 2021

R.S.B.
18/8/54
Lloyd's Register
Foundation

015163-015171-0256