

sp "Poljana".

It is submitted the Glasgow Surveyors should be requested to state whether the blow off cocks on the ships side are fitted with spigots & brass covering plates.

JM

JW

15/7/20

015183-015184-0402