

"JOHN BISCOE"

Before this case receives consideration IT IS SUBMITTED the Southampton Surveyors be asked for their comments on the following points:

- 1) Have the remote controls of the oil fuel pumps and oil fuel tank valves **been** fitted as required by the Rules. *Not to pumps*
- 2) Have stand-by means of circulating the main engines been provided. If so details should be forwarded for record purposes. *yes*
- 3) Is there a stand-by lubricating oil pump for the main engines. *OK 2 main Eng.*
- 4) Has the machinery spare gear been checked and found to comply with the Rules. *yes*
- 5) It is noted *yes* they have examined the starting air receivers. A sketch showing the scantlings should be forwarded to this Office.
- 6) It would appear that Nottingham First Entry Report No.384 covering Ruston Hornsby Generator Set has not been returned to this Office, and this should be done as soon as possible.

IT IS FURTHER SUBMITTED the London Outdoor Surveyors be asked to forward their First Entry Reports 4d and 13 on the Electrical Propulsion and Electrical Equipment of this vessel. X

For clong to Lon: - 14/11
Lon 28/11

Ent

[Handwritten signature]

13. 1. 49.



Lloyd's Register
Foundation

015198-015212-0061