

COPY

Lloyd's Register of Shipping.



Port of MONTEVIDEO.

May 31st., 1948.

This is to Certify *that I have*

Surveyed the wood moyor vessel "JOHN BISCOE", of London, 416 tons net register, whilst afloat, on account of (a) reported leakage into after ballast tank, and (b) damage on port side stated due to surging against quay fenders in this port on May 15/16 last;

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report, stating that all ^{temporary} repairs recommended by me have been completed to my satisfaction, and that I have Recommended that she be continued as classed in the Register Book, subject to further examination in drydock on arrival at a convenient home port,

being fit to ~~carry~~ proceed in safety.

J. G. Pickthall
(Acting) Surveyor to Lloyd's Register.

A Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
While the Committees of the Society use their best endeavours to ensure that the functions of the Society are executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any
liability whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its
Officers, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or
negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society.

© 2021

Lloyd's Register
Foundation

015148-015212-0064