

Chief Engineer Surveyor

4 E

Received from Chief Engineer Surveyor

15 MAY 1952

S NAME "LAXMI"

REPORT Bom.

No. 10158

remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)


~~REPAIRS TO ENGINES AND BOLTERS DUE TO DAMAGE THEREON~~

This vessel holds the notation of "Laid up pending Survey".

A Special Survey of the machinery has now been partly held, various minor repairs have been carried out, but some other repairs are necessary and the Surveyor states that work has at present stopped on the vessel and that she is laid up indefinitely.

IT IS SUBMITTED action be deferred, pending the completion of the Survey or further information.

© 2021



Lloyd's Register  
Foundation

015273-015283-0237 14.5.52.