

o Chief Surveyors.....

Received from Chief Surveyors.....

SEL'S NAME "TRANSFORD II" REPORT Trd No. 700


For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

re of Survey..... When due.....

With reference to endorsements dated 25.3.53. and 10.6.53. a letter has now been received from Lloyd's Agents' Surveyor at Fort de France, Martinique, indicating that the scored screwshafts were replaced without repair.

It is not clear whether the shafts repaired at Trinidad are the spare or working shafts, and IT IS SUBMITTED action be deferred and the Trinidad Surveyor be requested to clarify the position and, in the event of the repaired shafts being fitted, state whether a fresh record of survey might now be assigned.


18.6.53. 



© 2021

Lloyd's Register
Foundation

015302 - 015315 - 0375