

COPY

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

Rpt.No.D.6330



Port of Piraeus,

3rd February, 1954.

This is to Certify that

D.A.Parissis

the undersigned Surveyor to this Society did at the request of J.A.Saunders, Esq., Lloyd's Agent, Piraeus, attend on board the S.S. "AGIOS GEORGIOS" 4248 tons gross of Piraeus, on the 28th January, 1954 whilst this vessel lay afloat at Perama for the purpose of ascertaining, without prejudice, the nature and extent of damage stated to have been sustained on the 21st January, 1954 at Perama.

It was stated that at the time of the occurrence the vessel was lying moored on the quay and the "CYRENIA" was lying in a similar berth on the port side of the "AGIOS GEORGIOS". Heavy weather at 4.00 p.m. on the 21st January, 1954 caused a wire rope between the two vessels to part and damage was caused to fittings on the fore-castle deck of the S.S. "AGIOS GEORGIOS".

For full particulars please refer to ship's Log Book.

On examination by the undersigned the following damage was noted with recommendations for permanent repairs.

FOUND:

Fore-castle deck (port side).

1 cast iron rope lead fractured.

3 guard rail stanchions fractured and rails in way distorted.

2 awning stanchions fractured and distorted.

125 fms. $1\frac{1}{2}$ " wire rope strained and parted.

RECOMMENDED:

To renew.

To remove, fair and weld in place.

To remove, fair and weld in place.

To renew.

The above recommendations were made with a view to the vessel being placed in as good condition as before the said damage was sustained.

The cost of above repairs is estimated at Drs. 13,000,000 with 6 days to complete.

No repairs have been effected meantime.

Survey fees 845,000

Stamps 11,500

D.A. Parissis
Acting Surveyor to Lloyd's Register.

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly performed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."