

Port

OF ANSWER

Sea Co

Has Shaft been checked

Approved

BOARD

The class is subject to Metalock repairs to the forward end of the starboard main engine bedplate being examined by 12.58.

4E

26 SEP 1958


Received by Chief Engineer Surveyor..... Received from Chief Engineer Surveyor.....

SHIP'S NAME..... SUNNY PRINCE..... REPORT Ant No. 33915

CS Advanced.

Repairs.

IT IS SUBMITTED this vessel is eligible to remain as classed subject as above.



Lloyd's Register Foundation

015338-015347-01917

Parts now examined:-

Main Engine Port:-