

4 E

Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

NAME "TANDJONG OEBAN" REPORT Syd. No. 20422

of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/92.*)

~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

A survey with a view to classification with this Society has been partly held by the Sydney Surveyors.

Plans of the shafting and pumping arrangements have been considered in this Office and dealt with in separate endorsements.

In the meantime a General Examination has been held.

IT IS SUBMITTED that this vessel is eligible for the record "Examined 2.46".

Further action being deferred until the classification survey has been completed and the points referred to in endorsements dated 1.5.46, 17.5.46 and 21.5.46 have been dealt with.

015338-015347-0238

24.5.46

© 2021

Lloyd's Register
Foundation