

Boilers...
by Boilers...

Surveyed at...
(State name of Dock.)

Mort's Slipway.

Particulars of Classification
precisely as in Regis

Report No.

Port

CHARACTER.
* for Special Survey
Date of last Survey and of
Periodical Surveys.

M.V. "TANDJONG OEBAN".

Electrical Equipment.

Classification.

IT IS SUBMITTED the Sydney Surveyors be informed that their Rpt. No. 20422, dated 20.2.46., on the electrical equipment and the accompanying test certificates have been examined and in order that the classification of the vessel may receive full consideration, plans of the installation should be forwarded for approval. It should be pointed out that although the generators are such as merit acceptance in this instance, the temperature rise of the field winding of the main engine driven generator is slightly greater than that permitted by the Rules, and the voltage applied for the high voltage (dielectric) test in the case of the auxiliary engine driven generator is lower than the Rule requirements. The Surveyors should accordingly be requested to bring these points to the notice of the manufacturers to obviate their being repeated in future. It is concluded that the labelling of the fuses will be carried out as requested in the Secretary's letter of the 5th April, 1946.

Sa.

21.5.46.



© 2021
Lloyd's Register
Foundation

015338 - 015347 - 0239

015338 - 015347 - 0240

s Conte

on of funnel

adjusted under

usted under

key Boilers?

key Boilers?

key Boilers?

oe fitted at

t being effie

at the after

efficiently lub

after bearing

power fit

Yes.

nder

tions w

too he

ls and

ke chec

full l

ook, conseq

ple, B.S. 9,11,

ient co

is compl