


face as indicated in the Secretary's letter  
of 11. 5<sup>th</sup> M.V. to the Sydney Surveyors. Further,  
ification M.V. "TANDJONG OEBAN." ~~17~~ B

SYDNEY RPT. NO. 20422.

plan of straight shafting has been examined in  
connection with the above-mentioned report and  
proposed size of crank & straight shafting  
at the requirements of the Rules.

drawings of the Air Receiver and auxiliary  
line and its shafting should be furnished for  
consideration.

the plan of propeller (bronz) and shafting  
is noted and in order.



© 2021

noted  
Bell

17/5/46

015338-015347-0240

015338-015347-0241

Lloyd's Register  
Foundation