

Thickness of cylinder liners

Are the cylinders fitted with safety valves

Are the exhaust pipes a

ducting material

If the exhaust is led overboard near the waterline, what means are arranged to prevent water from being

m/v. "Trocas"

Rot 16574.

It is submitted that
this vessel is eligible for
THE RECORD. + LMC 6. 27. CL.
Oil Engines 4 SC. DA. 1204 NH.
6 Cy $32\frac{1}{4}$ - $59\frac{1}{16}$. 2 DB. 180 lb.

JWD.
8/7/27

Fal. 6677

Since leaving Rotterdam the vessel put into
mouth with a broken No 6 piston rod
the main engines.

The lower section of the Cylinder liner has
been renewed & a spare piston rod fitted.

GPR

JWD

8/7/27

© 2021
Lloyd's Register
Foundation

015338-015347-0305

Internal surfaces of the receivers be examined

Yes

What means are provided for clearing their inner surfaces

drain arrangement fitted at the lowest part of each receiver

Yes