

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegrams: Committee, London, Telex
Telex No.: 24305

Telephone: ROYal 9166

2nd March, 1961.

assn (S)
AH/BS

Dear Sir,

Steamer "SINCLAIR H-C"

I acknowledge receipt of your letter of the 20th February with its enclosure, the contents of which have been noted.

So far as the hull is concerned, for the proposed voyage it will be necessary for the ship to be found or placed in satisfactory condition as a result of examination in drydock.

So far as the machinery is concerned, the main gearing will require to be examined through the inspection doors, the turbine rotor journals examined and the pumping arrangements and electrical equipment dealt with as required by Circular No. 1959. In addition, the Boiler and Screwshaft Surveys should be held and all machinery tried under working conditions.

Yours faithfully,

Deputy Clerk to the
Classification Committee.

The Secretary,
NEW YORK.

P.S. I have to add that any Certificate issued should indicate that the ship is unclassified during the voyage.



© 2021

SPS due 7.60

Lloyd's Register

Classification

015348-015354-0055