

Surveyors.....

Received from Chief Surveyors.....

ME "SINCLAIR H. - C" REPORT N.Yk. No. 56179

For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR~~


Reports which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case but the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92).

Next Docking: S.R.L. ~~Exercise~~

NOTED.

Subject to keel plates Nos. 13 & 14 (wasted) being specially examined and dealt with as necessary at the next drydocking.

*AM*  
9.10.51



© 2021

Lloyd's Register

015348-015354 Foundation

ATIO

er Bo  
ydock

my  
-13  
cki