

11 15 3 1/8 40.0 15 3 1/8 40.0 ALL BRACKETS 1.00" THICK  
15 3 3/8 40.0 15 3 3/8 40.0 ALL BRACKET WELDS 3/8"

12 JUL 1940

(Reg. 1 U.S.)

(Received at London Office..... 19.....)

No. 222 Place Quincy, Mass. Date June 6, 1940

We request that the Committee of Lloyd's Register will instruct the Society's Surveyors to Specially Survey during Construction the Hull, Engines and Boilers of the Vessel No. 1491 building by Messrs. Bethlehem Steel Co. (Shipbldg. Div.) for Messrs. Sinclair Refining Company (Shipbldg. Div.) of Tons. Length 450'-0" Breadth 63'-6", Depth 34'-6" intended to be Classed Carrying Petroleum in Bulk

We undertake to arrange for every facility to be given to the Surveyors to carry out the duty in question, and we agree to pay the fees for the Surveyors' services, in addition to the actual travelling and other expenses incurred by the Surveyors in connection therewith.

This request is made upon the terms the Rules and Regulations of Lloyd's Register of Shipping, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Engine Makers DeLaval Steam Turbine Company

Boiler Makers The Babcock and Wilcox Company

Signature C. V. Cheneys

To the Principal Surveyor,  
Lloyd's Register of Shipping,  
17, Battery Place, New York.

General Manager

Bethlehem Steel Company (Shipbldg. Div.)

Quincy, Mass.

015348-015354-0088

Spacing of Transverse Frames .....

<sup>a</sup> State if joggled or liners.

Lloyd's Register Foundation

Spaci