

N.B. - All entries in the existing records should be...

BS*

Rpt. 14.

R.C.

Port of **SINGAPORE.**

2nd March, 1950

REPORT ON MASTS, SPARS, AND RIGGING.

Having, in accordance with your instructions, examined the Masts, Spars, Iron Work of same, and Rigging, of the

(Name of Vessel) **S. S. HONG ANN**

on the (Date of examination) **27th February, 1950.**

I have to report that I found **one defective bottle on Rigging screw of Fore Mast and 4 defective bolts on rigging screw shackles of Main Mast (Renewed).** Fore and Main Masts, Spars, Iron Work of same, Rigging, Screws and Shrouds are now in good condition.

Singapore Slipway & Eng: Co. Ltd.

J. M. Watt
Works Manager

Fee **\$20** :

To the Surveyors,
Lloyd's Register of Shipping,
Singapore

2m.12.47.



© 2021

Lloyd's Register
Foundation

015390-015404-0219

recommen^d that the indented upper vertical stem plate and shell plates 'E'...

boar
an L
Pervi
49
vey
and
after
dam
insc
ets
ue c
Chain
Howe
Stand
Sails