

11.48

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor

5 MAY 1950 4 E

VESSEL'S NAME

"HONG ANN"

REPORT

Sng.

No. 8118

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement. — Extract from Sub-Committee's Report, 24/5/52.)

Nature of Survey

~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

MBS due 10.49 now held.


Blr.S. due 10.49 now held.

Docking.

Minor wear and tear repairs effected.

IT IS SUBMITTED that this vessel is eligible
for the record MBS* 2.50, Blr.S. 2.50.

© 2021



Lloyd's Register
Foundation

5. 5. 50.

015390-015404-0223

doors and mountings and all found satisfactory. The safety valves were
adjusted under steam as stated above.