

COPY ONLY.

MORRIS HEDSTROM, LIMITED

SUVA, FIJI

25th October, 1956.

The Surveyors,
Lloyd's Register of Shipping,
4 Bridge Street,
SYDNEY

Dear Sirs,

"AI SOKULA"

We acknowledge receipt of your letter of the 16th instant and note therein that the owners are concerned that the surveyor states in his report that the boiler safety valves were adjusted to a pressure of 100 lbs. per square inch.

This question was referred to the surveyor, Mr. E. Bowyer Corbett, who now advises us as follows:

"This is to confirm that the "AI SOKULA" safety valves were set to 200 lbs. per square inch and not 100 lbs. per square inch as stated in the report - this was evidently a typographical error".

Kindly note.

We have corrected our copy of the report accordingly.

Yours faithfully,
MORRIS HEDSTROM LIMITED.

(H.O.E. PALMER)
SHIPPING MANAGER.



© 2021

Lloyd's Register
Foundation

015390-015404-0243