

COPY

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

38. S. 53



Port CASABLANCA (Morocco)

11th August 1953

This is to Certify that I have

Surveyed the Boiler ~~and Machinery~~ of the tug "SIDI BELYOUT"
of CASABLANCA - G.T. 292 -.

"

"

"

and that I have transmitted to the Committee of Lloyd's
Register of Shipping, London, a Report stating that all
recommendations made by me in connection therewith have
been carried out to my satisfaction, and that I have

Recommended that the record of B.S. 8.53

"

"

"

be made in the Register Book in the case of this vessel when
the survey has been completed.

Parts now examined:—

All parts of the boiler are in good condition.

In the center fire-box, one stay tube has been expanded. ²²⁰

The safety valves have been adjusted under steam at 180 lbs.

Heights of the safety casing { Starboard : 11 mm.
Port : 10 mm. |

LLOYD'S AGENCY



✓ of fire extinguishers
installed

See La Cab
on 16/9/53

[Signature]

Engineer Surveyor to Lloyd's Register.

Surveyor appointed by Lloyd's Agents.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."