

COPY.

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C.3.

10th February 1939.

Dear Sir,

E. With reference to Danzig First Entry report No.154 on the dredger "FU SHING", Messrs. F. Schichau's Yard No.1400, I have to point out that although the boilers were approved for a working pressure of 245 lb. per sq. inch, the shafting was approved for only 225 lb. per sq. inch. The shafting does not meet the requirements of the Rules for a pressure of 245 lb. per sq. inch, and I shall therefore be glad if you will make arrangements for the safety valves to be re-adjusted accordingly.

It is also noted that a deviation of 5 degrees has been observed on the standard compass and 3 degrees on the steering compass, due to the effect of switching on and off the electric circuits in the vicinity of these instruments. These deviations are excessive and steps should be taken to discover the source of the interference and to remedy it.

I am, Dear Sir,

Yours faithfully,

R. Shaw, Esq.,

DANZIG.



© 2021

Secretary.

Lloyd's Register
Foundation

015405-015416-0111