

COPY.

Lloyd's Register of Shipping

10 JAN 1944

No. of
2306.

ing power

eamen...or
use, and
very kind
Crew.

230.62 }
151.58 }
or whom
.....)

382

Port Vancouver, B. C.

September 29th, 1943.

Merchant
54 of the

vs. —
on

22.39 }
7.25 }
11.58 }
13.16 }
72.07 }
61.86 }
93.12 }

284.

ks

2972.

This is to Certify that I have

spaces framed in above the

ster tonnage...

of Bulkheads

ed the Steel Single Screw Steam Tanker, "MOUNT ROYAL PARK"

tons gross, during construction by Messrs. Victoria

inery Depot Co. Limited, Victoria, B. C. (Their Hull No. 29)

Service No.
Competency No.

that I have transmitted to the Committee of Lloyd's
ster of Shipping, London, a Report stating that all repairs
mended by me have been completed to my satisfaction, and

ister of Munitio
our (64) shares.

I have Recommended that she be classed * 100 A. 1.

of Bulkheads

reeboard "Carrying Homogeneous Cargo of Petroleum in

being fit to carry. Homogeneous Cargoes of Petroleum in Bulk.


D.S. Forsyth

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

(CERT. B.)



Lloyd's Register
Foundation