

This vessel is classed BS*

BC

Chief Surveyors.....

Received from Chief Surveyors.....

3
VESSEL'S NAME 'DESTRIAN' REPORT Liv. No. 129629

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

of Survey Docking & Damages. When due

NOTED.

Subject to bilge plate rivets (leaky) at after end of Engine Room (s.s.) being dealt with at the next dry docking.

BS*
9.49 Liv.

ENDORSEMENTS OF CLASS (B).

W.O.T.
11 49

✓ Indents in shell plating (p & s).
✓ Indents in No.2. D.B. tank top plating.



© 2021

Lloyd's Register
Foundation

015450-018460-0314