

1- APR 1964

Ship's name "HONGKONG VENTURE"

Port

NSW

No.

8417

Last survey date 6.3.64.

GB Class is subject to

damaged boat deck guard rails and stanchions etc. (p.s) also to centre girder connection riveting in keel plate on way of No.1 D.B. tank being specially examined and dealt with as necessary next drydocking.

ACTION is DEFERRED for S.S. by 4,64.

S.R.L. Appendix (~~XXXXXXXXXX~~ none)

Surveys due SPECIAL SURVEY (C) due 4,63. Postponement until 4,64 approved 28.1.64; following a satisfactory G.E.

Nature of present survey (afloat and in drydock)

Temporary repairs to leakage in shell plating in way of midship deep tank (p.s).

Is interim certificate in order

Yes/No/None

Items outstanding if any for SS

ALL ITEMS.

SS proposed to be completed by

4,64.

Recommendation

SUBJECT as above, and to shell plates G.11 & H.11 (p.s. amids.) being specially examined and dealt with as necessary next drydocking but further ACTION be DEFERRED for S.S. by 4,64.

SUBJECT



© 2021

Lloyd's Register
Foundation