

21 DEC 1967 - 6 DEC 1967

Ship's name "FATEHABAD" Port Chg No. 1192  
Last survey date 24.10.67  
Class is subject to indented shell plates (s) in 2nd, 3rd & 4th  
strakes below sheer and structure in way of E.R. and B.R.,  
to fractured shell plate J.7 (sP (temp.repaired) and to  
wasted shell plating in No.4 hold (s.a) and No.5 hold (s.f)  
being specially examined and dealt with as necessary by 11,67,  
to shell plate H.18 (s) frs.144/148 (doubler fitted) and set in  
bulwark plating (p.f) and superstructure (p.amids & aft) being  
specially examined and dealt with as necessary by S.S. & to  
S.R.L. Appendix (as before or none) doubled shell ptg. in No.1 hold (pa)  
Surveys due being specially examined and dealt with as necessary  
(next drydocking).

SPECIAL SURVEY (D) due 4,67. Postponement until 11,67  
approved 14.9.67 after G.E. held.

Nature of present survey (afloat ~~and in drydock~~)

Permanent repairs to damage (cargo).  
Transfer of spare bower anchor to other vessel.

Is interim certificate in order

Yes/No/None

Items outstanding if any for SS

ALL ITEMS

SS proposed to be completed by 11,67

Recommendation

SUBJECT as above, and to a spare bower anchor  
being supplied at the earliest opportunity  
but ACTION be DEFERRED for S.S. by 11,67.

SUBJECT

*Verified*

