


COPY

LLOYD'S REGISTER OF SHIPPING



6150

Port **B r e m e n**

Received from Chief Engineer Surveyor
9th September, 1961

Engineer Surveyor are desired on this case for the consideration of the Clasing Committee.
and summary of any repairs that have been required and to show the causes or causes of such repairs, and also to bring
in connection with the case, so that the Clasing Committee may have all the salient points presented in the
Committee's Report, 24(192)

This is to Certify that I have
Surveyed the Machinery of the M/T "NOBILPET" 499 tons gross of London
(Rolandwerft GmbH, Bremen, Yard No.890) whilst building on stocks and
afloat at Rolandwerft, Bremen-Hemelingen, on the 30th May, 1961 and
subsequently,

and that I will transmit to the Committee of Lloyd's Register of
Shipping, London, a Report stating that all recommendations made by
me in connection therewith have been carried out to my satisfaction; also
that I will Recommend that in the case of this Vessel the following
Survey Records be made in the Supplement to the Register Book

+Lloyd's LMC 9/61

and that her Machinery Classification Record be continued in the Book. accordance
subject to satisfactory examination of vessel upon arrival at
Thames. the approved plans, and it is submitted she is

Parts now examined:
(C.S. Items only)

H. Bornholdt

Engineer Surveyor to Lloyd's Register
(H. Bornholdt)

KEY TO ABBREVIATIONS

ABS	Auxiliary Boiler Survey	SGS	Steam Generator Survey
CS	Continuous Survey of Engines	SPS	Steampipe Survey
DBS	Donkey Boiler Survey	TS	Tailshaft Survey
ES	Engine Special Survey	TS(CL)	Tailshaft Survey—Continuous Liner
MBS	Main Boiler Survey	TSN	Tailshaft renewed
MES	Modified Survey of Oil Engines	TS(OG)	Tailshaft Survey—Oil Gland
OF	Fitted for oil fuel (date) FP above 150°F.		

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Cert. B.1.) 150m,3,59 (MADE AND PRINTED IN ENGLAND.)

016275-016672-0068