

COPY

# LLOYD'S REGISTER OF SHIPPING

Part of ROTTERDAM,

23rd November, 1960

*All amended  
best.*

This is to Certify that I have

surveyed the Machinery of the M.S. "GOLDEN COMET", 1279,52 tons gross  
of Guernsey, Messrs. De Waal's Yard No. 670 whilst fitting out at  
Messrs. "De Waal" at Zaltbommel . . . . .

and that I will transmit to the Committee of Lloyd's Register of  
Shipping, London, a Report stating that all recommendations made by  
me in connection therewith have been carried out to my satisfaction; also  
that I will **Recommend** that in the case of this Vessel the following  
Survey Records be made in the Supplement to the Register Book  
Lloyd's L.M.C. 11-60 O.G. "Oil Engines"

and that her Machinery Classification Record be continued in the Book.

parts now examined: (C.S. Items only)

*A. van Hasselt*  
Engineer Surveyor to Lloyd's Register.  
A. van Hasselt.

KEY TO ABBREVIATIONS

- |     |                                            |        |                                   |
|-----|--------------------------------------------|--------|-----------------------------------|
| ABS | Auxiliary Boiler Survey                    | SGS    | Steam Generator Survey            |
| CS  | Continuous Survey of Engines               | SPS    | Steampipe Survey                  |
| DBS | Donkey Boiler Survey                       | TS     | Tailshaft Survey                  |
| ES  | Engine Special Survey                      | TS(CL) | Tailshaft Survey—Continuous Liner |
| MBS | Main Boiler Survey                         | TSN    | Tailshaft renewed                 |
| MES | Modified Survey of Oil Engines             | TS(OG) | Tailshaft Survey—Oil Gland        |
| OF  | Fitted for oil fuel (date) FP above 150°F. |        |                                   |

is issued upon the terms of the Rules and Regulations of the Society, which provide that:—  
The Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed,  
and that neither the Society nor any Member of its Committees is under any circumstances whatever to be held  
responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book  
of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof,  
or for any error of judgment, default or negligence of any of its Committees or any Member thereof,

016275-016672-0166