

ANNUAL SURVEYS.

596

No. 596 Survey held at Aberdeen Date 6th December 1839
on the Schooner Superior Master Thomas Smith
Tonnage 143 Built at Lyme When built 1816
By whom built Richard Bussel Owners Hull Shipping Company
Port belonging to Aberdeen Destined Voyage London
If Surveyed Afloat or in Dry Dock Surveyed Afloat

Original Survey, No. 449 Port of Aberdeen 13th November 1838 Classed A.T.

The Surveyor is required to state the present Condition of the as far as can be seen Patent

Decks	Breasthooks	Capstan <u>Winch</u>
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge)	Anchors No. of <u>2 Bower / 1 Stream / 1 Kedge</u>
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper <u>Single Bottom</u>

General Observations and Opinion, Has received no particular repairs only caulking and the
as required by the Instructions, necessary overhaul in the rigging and sails.

Wm Christie

Committee Minute 3 Jan 1840

Character assigned A.T.

No. 597 Survey held at Aberdeen Date 9th December 1839
on the Schooner Nimrod Master James Marsh
Tonnage 144 Built at Bridport When built 1817
By whom built Richard Bussel Owners A. & W. Phillips
Port belonging to Aberdeen Destined Voyage Newcastle
If Surveyed Afloat or in Dry Dock Surveyed Afloat

Original Survey, No. 485 Port of Aberdeen 19th November 1838 Classed A.T.
21, 162 Abn. Lon. 1022, Abn. 272, 368, 485 The undermentioned Articles are all in good condition

Decks	Breasthooks	Capstan <u>Winch</u>
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirkettling	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank & Treenails (Outside to the Water's Edge)	Anchors No. of <u>2 Bower / 1 Stream / 1 Kedge</u>
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper <u>Single Bottom</u>

General Observations and Opinion, Has received no particular repairs only caulking and
as required by the Instructions, the necessary overhaul in the rigging and sails.

Wm Christie

Committee Minute 3 Jan 1840

Character assigned A.T.



© 2021

Lloyd's Register
Foundation