

# ANNUAL SURVEYS.

No. 424 Survey held at Aberdeen Date 26<sup>th</sup> December 1840  
 on the Galliot Katharina Master C. Reinbrecht  
 Tonnage 83 Built at Hamburg When built 1835  
 By whom built J. P. Loepp Owners C. Reinbrecht  
 Port belonging to Hamburg Destined Voyage Stockton  
 If Surveyed Afloat or in Dry Dock Surveyed Afloat

In the Register Book. Original Survey, No. 2807 Port of London 1836 Classed A.T.

The Surveyor is required to state the present Condition of the *The undermentioned Articles are all in good condition as far as can be seen*

Decks	Breasthooks	Capstan
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirketting	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank and Treenails (Outside to the Water's Edge)	Anchors No. of <u>2 Bower / Stream / Kedge</u>
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass	Copper <u>Single Bottom</u>

General Observations and Opinion, *Has received no particular repairs only caulking and the necessary overhaul in the Rigging and Sails.*  
*Wm. Chene*

Committee Minute 5<sup>th</sup> January 1834

Character assigned *[Signature]*

No. 425 Survey held at Aberdeen Date 28<sup>th</sup> December 1840  
 on the Schooner Nimrod Master John Robertson  
 Tonnage 144 Built at Bridport When built 1814  
 By whom built Richard Russel Owners A. & S. Phillips  
 Port belonging to Aberdeen Destined Voyage Newcastle  
 If Surveyed Afloat or in Dry Dock Surveyed Afloat

Original Survey, No. 411, 163 Port of Aberdeen London 1822, Abn 272, 368, 485, 596. Classed A.T.

The Surveyor is required to state the present Condition of the *The undermentioned Articles are all in good condition as far as can be seen*

Decks	Breasthooks	Capstan <u>Potent winch</u>
Upper Deck Beams & Fastenings	Transoms	Pumps
Lower Deck Beams & Fastenings	Timbers of the Frame	Masts, Yards, &c.
Spirketting	Topsides	Sails
Plank Shears	Wales	Cables
Waterways	Plank & Treenails (Outside to the Water's Edge)	Anchors No. of <u>2 Bower / Stream / Kedge</u>
Hatchway Comings	Rudder	Standing & Running Rigging
	Windlass <u>Potent</u>	Copper <u>Single Bottom</u>

General Observations and Opinion, *Has received no particular repairs only caulking and the necessary overhaul in the Rigging and Sails.*  
*Wm. Chene*

Committee Minute 5<sup>th</sup> January 1834

Character assigned *[Signature]*