

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report *May 29 1893* When handed in at Local Office *May 29 1893* Port of *Meriden*
No. in Reg. Book *Survey held at Meriden* Date, First Survey *May 26* Last Survey *May 29 1893*
on the *Wood, Iron or Steel S.S. "North Star"* (No. of Visits *3*) Master *✓*

TONNAGE: Built at *Meriden* By whom *J. Duttie Sons & Co* When *1883* YEAR MONTH
GROSS *126* Owners *H. Pappert* Port belonging to *Meriden*
UNDER DK. *115*
NET *11* Owners' Address
(if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? *Dry dock* Name of Dock *Am dry dk* Destined Voyage *Trawling*

WB=DBa tons; f tons; u.E&B tons; CellDB tons; Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
FPT tons; APT tons; MT tons.

N.B.—All alterations in the existing records should be underlined.

Last Survey, No. *4118* Port *Meriden*

CHARACTER. * for Special Survey. Date of last Survey and of Periodical Surveys.	Years Assigned expired.	Machinery and Boiler Surveys (including date of N.B., if any).
<i>100 A1 7.92</i>		<i>7.92</i>
<i>Stm Trawler</i>		<i>7.92</i>
<i>S.S. "North Star"</i>		

Society's Freeboard (if assigned) as painted on Ship and now verified } ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR *Fitting Rolling Chocks*

The vessel placed in the above dry dock, the bottom examined, and found in good condition, and afterwards repainted.

Rolling chocks of 4 1/2" bulb, fitted on each side, for a distance of 20ft, between double angles 3" x 3 1/2".

SUMMARY OF DAMAGE REPAIRS: — Plates, Fair'd or Repaired; Frames, ditto. Plates, Renewed; Frames, ditto. Other Repairs *Fitting Rolling Chocks*

PRESENT CONDITION OF THE

Decks <i>Good</i>	Transoms, Pointers, & Crutches <i>Good</i>	Copper, or Y.M. (State if on Felt.)	Hatches <i>Good</i>
Waterways	Timbers of Frame at the openings	When put on, Month Year	Boats
Coamings	Ditto ditto at other places	Rudder <i>Good</i>	Masts, Yards, &c.
Up'r Dk. Beams & Fastenings	Keelsons	Windlass & Capstan	Condition, how ascertained <i>Good</i>
Low'r Dk. Beams & Fastenings	Clamps, Shells & Stringers	Pumps	Sails
Plating	Salting (State if examined.)	Engine Room Skylights	Equipment letter <i>6</i>
Planking	Ceiling	Coal Bunker, Open'gs, Lids, &c.	Anchors, No. of <i>2 B. 1 S. 1 K</i>
Treenails or Rivets	Cement or Asphalt (State which.)	Scuppers	Cables (State if now ranged) <i>Yes</i>
Breasthooks & Stemson	Tanks (State if now tested.)	Cargo & Main H'tch'wys	" length <i>120ft</i> size <i>1 1/2"</i>
	Caulking of Bot'm, D'k, & Wat'r'wys		" Rule length <i>120ft</i> size <i>1 1/2"</i>
			Hawsers & Warps <i>Good</i>
			Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 9,91," or "to remain as classed and to have record of survey, 9,91, and the notations of ss No. 1-91 and ptND91, &c."

This vessel so far as seen is now in good and efficient condition, and eligible in my opinion to remain as classed, and to be noted 5. 93 in the Register Book.

Office Fee (if chargeable) per Sect. 11, Sec. 27	£	Fees applied for,
Survey Fee (per Section 28)	£	<i>May 29 1893</i>
Special Damage or Repair Fee (if any) (per Sec. 28.)	£ <i>14/9/93</i>	Received by me,
Travelling Expenses (if chargeable)	£	<i>28. 9. 18. 93</i>
Second Surveyor's Fee (if any)	£	<i>29. 9. 93</i>

G. Lisle Hindmarsh
Surveyor to Lloyd's Register of British & Foreign Shipping.

Is Certificate now required?
Committee's Minute
Character assigned

FF 2 JUN 1893

100A1 Stm Trawler



FRI 14 JUL 1893

Lloyd's Register Foundation

Is a Report also sent per on the Machinery of the ship? If not, state whether, and when, one will be sent?

Certificate, if required, to be sent to

Form No. 2 for Register (The Surveyor's Report requested not to be used for Committee's Minute)

reps.