

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report Sept 14th 1898 When handed in at Local Office Sept 14th 1898 Port of Aberdeen

No. in Survey held at Aberdeen Date, First Survey Sept 9th 1898 Last Survey Sept 9th 1898

Reg. Book. 1267 on the Wood, Iron or Steel S.P. Craigellachie Master W. Craig

TONNAGE:-

GROSS

UNDER DE

NET

Built at

By whom

When

Owners

Port belonging to

Owners' Address

(If not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock? Both Name of Dock Aberdeen Destined Voyage Fishing

WB=CellDBoDBo feet; uE&B feet; J feet; total capacity tons. FPT tons; APT tons; MT feet tons.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

N.B. All alterations in the existing records should be underlined. If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 5751 Port Abn

CHARACTER.	Year Assigned	Machinery and Boiler Surveys
For Special Survey.		(including date of N.B., if any).
Date of last Survey and of Periodical Surveys.		
+ 100A - For Fishing + LMC. 1. 96		
Purposes 4. 98		

Society's Freeboard (if assigned) as painted on Ship and now verified

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Condition
The bottom, sea connections, & propeller fastenings
examined, found satisfactory, cleaned &
painted.

SUMMARY OF DAMAGE REPAIRS:-

Renewed

Removed and Faird or Repaired

Faird or Repaired in place

Plates.

Frames.

R. Frames.

Floors.

Beams.

Str. Plates.

Dk. Plates.

Other Items:-

PRESENT CONDITION OF THE

Decks

Caulking of Decks

Waterways

Coamings

Beams & Fastenings

Outside Plating

Caulking of ditto

Rivets

Breasthooks & Crutches

Transoms

Frames

Reverse Frames

Floors

Keelsons

Stringers

Inner Bottom Plating

State if Tanks now tested

Bulkheads

Ceiling

Cement or Asphalt

(State which.)

Rudder

Windlass

Have Pumps now been examined and found efficient?

Have Sluice Valves now been examined and found efficient?

Have Watertight Doors now been examined and found efficient?

Have Watertight Doors now been examined and found efficient?

Have Watertight Doors now been examined and found efficient?

Have Watertight Doors now been examined and found efficient?

Engine Room Skylights

Coal Bunkers, Open'gs, Lids, &c.

Scuppers

Cargo Hatchways

Hatches

Planking of Wood Vessels

Treenails

Breasthooks & Stemson

Transoms, Pointers, & Crutches ditto

Timbers of Frame at openings ditto

Ditto ditto at other places ditto

Stringers, Clamps & Shells ditto

Salting

(State if examined.)

Copper, or Y.M.

(State if on felt.)

When put on Month Year

Boats

Masts, Yards, &c.

Condition, how ascertained

(State if wedges removed)

Sails

Equipment letter

Anchors, No. of

Cables (State if now ranged)

length

(on board)

Rule length

(per Table 22)

Hawsers & Warps

Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:-

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:- "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1.98," or "to remain as classed and to have record of survey, 1.98, and the notations of ss No. 1-98 and ptND98, &c."

This vessel appears to be in good
condition, eligible in my opinion to
remain as classed with fresh record of
9.98 in the Reg Book -

Office Fee (if chargeable) per Scale II., Sec. 27

Survey Fee (per Section 28)

Special Damage or Repair Fee (if any)

Travelling Expenses (if chargeable)

Second Surveyor's Fee (if any)

Fees applied for,

18

Received by me,

18

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute

Character assigned

FRI. 16 SEP 1898

100A -

for fishing purposes.



© 2019

Lloyd's Register Foundation

ABN15-0305