

No. 6392

(Received at London Office,

TESTS OF BOILER STEEL.

Tests of 2 Steel Plates manufactured by Messrs D Colville & Sons of Motherwell for Boiler No. 247 to be constructed by Messrs Hall Russell & Co of Aberdeen for the S.S. No. 247.

Date first visit January 24 1888 last visit February 3rd 1888 No. of visits

The _____ specified in the accompanying copy of Advice Notes were rolled from _____ charges. The tensile test has been applied to _____ samples as set forth below, and the temper and bending tests to a shearing from each plate with satisfactory results.

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins.	Remarks.
					Thickn.	Brdth.	Area.	Total.	Sq. Inch.		
					Ins.	Ins.	Ins.	Tons.	Tons.	%	
<p>Note:- These two plates are part of a batch reported on the 26th January Report No. 6303</p>											
<p><i>Alb</i> 8.2.88</p>											

Fee £ : :

Expenses £ : :

£ : :

To be paid by



© 2021

H. M. Done
Surveyor, Lloyd's Register,
Glasgow
4-2-88