


No. 4528

(Received at London Office,

TESTS OF BOILER STEEL.



Tests of 3 Steel bars manufactured by The Steel Co<sup>y</sup> of Scotland of  
for Boiler No. 4/88 to be constructed by Hall, Russell & Co<sup>y</sup> of Aberdeen.  
for S.S. "Dabulameugi".

Date first visit 30-4-88 last visit 11-5-88 No. of visits ✓

The \_\_\_\_\_ specified in the accompanying copy of Advice Notes were rolled from \_\_\_\_\_ charges. The tensile test has been applied to 2 samples as set forth below, and the temper and bending tests applied to one piece with good results.

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plate or bars in same charge	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins. %	Remarks.
					Thickn.	Brdth.	Area.	Total	Sq. Inch		
					Ins.	Ins.	Ins.	Tons.	Tons.		
1	Stay bars 2 dia	B464		626	1.18 dia	1.094	31.9	29.1	29		
2	" 3 1/4"	E117		278	1.19	1.112	31.6	28.4	35.5		

DP  
17/5/88

Fee ..... £ : :  
Expenses £ : :  
£ : :

To be paid by



12-5-88