

(Received at London Office,

Tests of 1 Steel plate manufactured by The Steel Co. of Scotland of Blochairn
for Boiler No. 488 to be constructed by Messrs. Russell & Co. of Aberdeen
for the S.S. "Sakulamenzi";

Date first visit 26/5/88 last visit 31/5/88 No. of visits

The _____ specified in the accompanying copy of Advice Notes were rolled from _____ charges. The tensile test has been applied to _____ sample as set forth below, and the temper and bending tests satisfactory

[illegible]

Expenses £ : :

£ : :

To be paid by

Surveyor, Lloyd's Register,