

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME

Hon S. H. Katheru

Rpt.

Abu

No. 11013

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

2nd S.S. No. 3.

THICKNESSES OF PLATING ascertained by drilling, and comparison of same with the original thicknesses.

The thicknesses are in $\frac{16}{16}$ of an inch.

STRAKE.	AMIDSHIP.					FORWARD.					AFT.					REMARKS.
	Original Thickness.	Thickness by drilling.		Diminution if any.		Original Thickness.	Thickness by drilling.		Diminution if any.		Original Thickness.	Thickness by drilling.		Diminution if any.		
		Port.	Std.	Port.	Std.		Port.	Std.	Port.	Std.		Port.	Std.	Port.	Std.	
	Ins.	In.	In.	In.	In.	Ins.	In.	In.	In.	In.	Ins.	In.	In.	In.	In.	
SPAR SHEER STRAKE																
Strake below.....																
MAIN SHEER STRAKE	10	10	9	-	1	7	7	7	-	-	7	8	8	f	-	-
1st Strake below	7	7	7	f	-	5	5	5	6	6	5	5	5	-	-	-
2nd " "	7	6	6	f	16	16	6	5	5	1	1	6	6	6	6	6
3rd " "	8	7	7	6	16	16	5	6	6	-	-	5	6	6	5	-
4th " "						6	7	7	-	-	6	7	7	-	-	-
5th " "						5	5	5	f	-	-	5	7	7	-	-
6th " "																
7th " "																
8th " "																
9th " "																

b = bare

f = full

b = bare
 f = full

The 2nd s.s. No. 3 has now been held and the plating drilled with results as shewn above, and it is submitted they may be considered satisfactory.

The following repairs have been done due to wear and tear:— several frames and reverse frames repaired; 14 deck plates renewed; the hatchway coamings, beams, etc. repaired; a shoe plate fitted aft; a number of rivets renewed and minor repairs done.

It is submitted the vessel appears worthy to remain as classed with record of survey and notation of 2nd s.s. No. 3 as recommended.

100A-1

12-12 Abu

S. H. Abu 2nd No 3 12-12

Transfer

Survey Fee (per Section 98)

2

5 : 0 : 0.

Fees applied for,

12-12-1912

2019
 Lloyds Register
 Foundation

ABN 22-0122