

C. 570.

Liverpool
June 30th/13.

James E. Milton

Sir - The Liverpool Refrigeration Co. Ltd
attend their works at Warrington on June 6th
and subsequently on June 26th, for the purpose
of examining and testing the Condenser and
Evaporator Coils originally fitted in the
Refrigerating installation (Ammonia) of the
S.S. "Oakwood" and now intended for the
S.S. "Armidale".

Upon examination, the undersigned
found the Evaporator Coils were exceedingly
corroded and deeply pitted locally & one
Condenser Coil much chafed at one spot.
Two Coils were split & one of them
test.. It was recommended that new
Evaporator Coils be made & tested, & the
Condenser Coils be repaired and afterwards
be tested..



© 2019

Lloyd's Register
Foundation

ABN32-0172

In the 2nd inst, the Undersigned examined
and tested by hydraulic pressure of 1000 lbs per
sq in, the new sets of Evaporator coils (five
in each set, 1 1/2" dia. 1 1/2" bore 1'6" gauge), and
four condenser coils, after repair and galvanizing
(1 1/2" dia. 1 1/2" bore), with satisfactory
results.

The above coils have now been forwarded
to Aberdeen where they are to be fitted
on board.

J. B. Milton

£22.0
Repair &c.
£2.5.6



© 2019

Lloyd's Register
Foundation

ASIN 52-14252