

Address,

RDEEN"



& Co

UILDERS.

eyors,

oyds Register,

A B E R D E E N .

S,

S. S. "Armida"

This vessel No.1394 in your last register has just been
 d by new owners who are replacing the present boilers by
 work at 160lbs working pressure. The new Owners have
 ed us regarding the tripling of the main engines, and it
 sted to fit a new H.P. cylinder about 19 inches in diameter
 op of the present H.P. cylinder.

It is desired to carry out this alteration without altering
 s of the present shafting and other parts, and we should be
 if you can inform us if this will be approved.

We understand that while your register gives the present
 s as $\frac{32'' \times 59''}{33''}$ that a new liner was fitted in the smaller
 some time ago reducing it to 29" diameter.

As the matter is urgent we should be glad to have a reply
 as possible.

Yours faithfully,

HALL, ROSS & CO., LTD.

A. Hall Wilson

© 2019

Lloyd's Register
Foundation

ABN/32-0179