

ANNUAL SURVEYS.

No. 1799 Survey held at Barr Date March 4th 1850
 on the Brig Coquette Master Wm Bruce
 Tonnage 193 Built at Sunderland When built 1839
 By whom built Wm Hall & Co Owners Robert Simpson & Co
 Port belonging to Barr Destined Voyage Newcastle & Mersey
 If Surveyed Afloat or in Dry Dock On present Ship

Last Survey, No. 1000 Port of Newcastle Classed G.A. 1

The present Condition of the

Decks <u>Good</u>	Treenails <u>Good part new</u>	Windlass and Capstan <u>Good</u>
Waterways <u>Good</u>	Breasthooks and Stemson <u>Good</u>	Pumps <u>2 Good</u>
Comings <u>Good</u>	Transoms, Pointers, and Crutches <u>N"</u>	Boats <u>2 Good</u>
Upper Deck Beams & Fastenings <u>Good</u>	Timbers of the Frame <u>where seen</u>	Masts, Yards, &c. <u>Good</u>
Lower Deck Beams & Fastenings <u>Good</u>	Keelsons <u>Good</u>	Sails <u>Good part new</u>
Planksheers <u>Good</u>	Clamps and Shelves <u>N"</u>	Anchors No. of <u>4 Good</u>
Sheerstrakes <u>N"</u>	Ceiling <u>N"</u>	Cables <u>100 fathoms Good</u>
Topsides <u>N"</u>	Rudder <u>N"</u>	Hawsers and Warps <u>Good</u>
Wales <u>N"</u>	Copper <u>new</u> When put on <u>1850</u>	Standing & Running Rigging <u>Good</u>
Plank (Bottom) and Counter <u>Good</u>		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways Good

This vessel has been well overhauled including spars, rigging &c. The fine sheathing stripped off the bottom & a number of new treenails introduced below the wales. The bottom scraped from keel to gunwale including planksheers, waterways & deck all over. The bottom resheathed with zinc & felt.

Committee's Minute 9th March 1850

Character assigned Rest 12

Wm. Hall
 A Certificate (if required)

No. _____ Survey held at _____ Date _____ 185____
 on the _____ Master _____
 Tonnage _____ Built at _____ When built _____
 By whom built _____ Owners _____
 Port belonging to _____ Destined Voyage _____
 If Surveyed Afloat or in Dry Dock _____

Last Survey, No. _____ Port of _____ Classed _____

The present Condition of the

Decks _____	Treenails _____	Windlass and Capstan _____
Waterways _____	Breasthooks and Stemson _____	Pumps _____
Comings _____	Transoms, Pointers, and Crutches _____	Boats _____
Upper Deck Beams & Fastenings _____	Timbers of the Frame _____	Masts, Yards, &c. _____
Lower Deck Beams & Fastenings _____	Keelsons _____	Sails _____
Planksheers _____	Clamps and Shelves _____	Anchors No. of _____
Sheerstrakes _____	Ceiling _____	Cables _____
Topsides _____	Rudder _____	Hawsers and Warps _____
Wales _____	Copper _____ When put on _____	Standing & Running Rigging _____
Plank (Bottom) and Counter _____		

General Observations and Opinion,

Caulking of Bottom, Deck, and Waterways _____

Committee's Minute _____ 18

Character assigned _____



© 2021

Certificate (if required).


Lloyd's Register
 Foundation

1799 Abn

Several parts of Ceiling in lower hold & between
Decks repaired. The pintles & braces of timber in the
fastenings. The Vessel is now in a good & efficient state
and is in my opinion Eligible to remain as above,

Fees received, for Registering repairs,
& for Certificate, £12. 6.

Wm. Wallis.



© 2021

Lloyd's Register
Foundation