

# REPORT of SURVEY for REPAIRS.

No.                      Survey held at London Date Feb 7. 16<sup>th</sup> 18 63  
on the "The Colleen Bawn" Master W<sup>m</sup>. Allen  
Tonnage 386 Built at Aberdeen When built 1861  
By whom built Hall Owners W<sup>m</sup>. Allen  
Port belonging to Adelaide Destined Voyage                       
If Surveyed Afloat or in Dry Dock in Bridge Dock

Last Survey, No. 2006 Port Aberdeen Classed 9 A1  
amended Report. 9.61

## REPAIRS

Stripped yellow metal sheathing, caulked from keel to metal line and re-sheathed with yellow metal over felt.

## Present Condition of the

Decks Good

Waterways                     

Comings                     

Upper Deck Beams & Fastenings                     

Lower Deck Beams & Fastenings                     

Planksheers                     

Sheerstrakes                     

Topsides                     

Wales                     

Plank (Bottom) and Counter                     

General Observations and Opinion,                     

Treenails Good where seen

Breasthooks and Stenson good

Transoms, Pointers, and Crutches "

Timbers of the Frame at the Openings

Do Do at other places not seen

Keelsons where seen good

Clamps and Shelves                     

Ceiling where seen "

Rudder                     

Copper F.Y.M. When put on 1863

Caulking of Bottom, Deck, & Waterways. when tested good

Windlass and Capstan Good

Pumps                     

Boats                     

Masts, Yards, &c.                     

Sails                     

Anchors No. of 3 B, 1 S, 1 K

Cables                     

Hawsers and Warps                     

Standing & Running Rigging                     

The Amount of Fee.....£                     

Special..... 1 : 1 : 0

Certificate (if required)                     

Committee's Minute                     

Character assigned                     

18

is received by me, John Maxwell



© 2021

Lloyd's Register  
Foundation