

Report of Survey for Repairs of Engines and Boilers.

(Received at London Office, RECEIVED 27th FEB. 89)

No. 405

No. in Reg. Book. 277 Survey held at South Shields Date, first Survey 20 Feb'y Last Survey 20th Feb'y 1882 on the Machinery of the S.S. "Ben Aron" (Number of Visits one)

Tonnage, Gross 632

Built at Aberdeen

When built 1875

Ditto, Net 402

Owners J. & A. Davidson

Port belonging to Aberdeen

Diameter of Cylinder 24" 40"

Engines made by Hall Russell & Co

When made 1875

Length of Stroke 30"

Boilers made by " "

When made 1875

Pressure of Steam 65 lbs

If Surveyed Afloat or in Dry Dock Edwards Dock

Years assigned. Character in Register Book.

Registered Horse Power 80 H.P.

Classed 90 A 1 9, 80

Last Survey No.

Port

Particulars of Repairs and Examination of sea cocks and propeller the vessel being in Dry Dock
(State cause of Repairs.)
Sea cocks overhauled examined & found in
propeller examined and found satisfactory
stem bush down 1/8"

General Observations, Opinion, and Recommendation:— As far as seen the machinery of this vessel is now in good order and safe working condition and eligible in my opinion to remain as classed

Entry or Registering Fee... £ - : - :-

Survey Fee (per Section 28) ... £ - : - :- received by me,

Certificate (if required) ... £ - : - :- 188

(Travelling Expenses, if any, £ - : - :-)

Committee's Minute 188

Assigned

Thomas Wilson
Engineer Surveyor to Lloyd's Register of British & Foreign Shipping.

Lloyd's Register Foundation

ABN7-0280

The survey is an
compilation of that
commenced at
Abandon (See
Rep Abn No.

1287M
28/2/22



© 2019

Lloyd's Register
Foundation