

REPORT of SURVEY for REPAIRS, &c.

(Received at London Office, RECEIVED 27th FEB. 82.)

No. 3388

No. in Survey held at
Reg. Book.

Aberdeen

Date, first Survey

July 15

Last Survey

July 24

1882

Master

YEAR.

MONTH.

30 on the

Ballater Iron Screw

TONNAGE under Tonnage Deck

599.

Ditto of Spar Deck, or Awning Deck

Ditto of Poop

Ditto of Raised Qr. Dk.

Ditto of Houses on Deck

Ditto of Forecastle

Gross Tonnage

741.

Crew Space, as per Rule

Register Tonnage, cut on Beam

Engine Room

Reg. Tons as St' mer, cut on Bm.

471.

Length of Poop

ft.

Ditto, Forecastle

ft.

Ditto, Raised Quarter Deck

ft.

Years assigned.

Character in Register Book.

Last Survey, No.

27462

REPAIRS, OR EXAMINATION AS PER RULE

Port Iron

Classed

1000-1

Cause of Repairs to be clearly stated.

Renewed, About 600 feet of Ceiling in holds. Caulked flat of deck. And for damage, doubled one plate on Starboard bow

Present Condition of the

Decks

Good

Waterways

"

Comings

"

Upper Deck Beams & Fastenings

"

Lower Deck Beams & Fastenings

"

Planksheers

"

Sheerstrakes

"

Topsides

"

Wales

"

Plank (Bottom) and Counter

"

Engine Room Skylights

Good

Coal Bunker, Openings, Lids, &c.

Good

Scuppers

Good

Cargo and Main Hatchways

Good

Hatches

Good

General Observations, Opinion as to Class, &c.

This vessel appears on examination to be in good and efficient condition and is eligible on my opinion to remain as classed

The Amount of Entry Fee ...

£

:

:

received by me,

Special ...

£

:

:

July 25 1882

Certificate (if required)

to be sent as per margin...

£

:

:

(Travelling Expenses, if any, £ none)

Committee's Minute

Tuesday, February, 28th 1882.

Character assigned

B.S. 2, 82

d 28/2/82

J. W. Kettle

Surveyor to Lloyd's Register of British and Foreign Shipping.



© 2019

Lloyd's Register Foundation