

REPORT of SURVEY for REPAIRS, &c.

Received in London Office,

THURSDAY 16 OCT 1884

No. 3558

No. in Reg. Book. Survey held at

Date, First Survey 23 Sept Last Survey 25 Sept 1884

on the "Klyde" Iron Steamer

(No. of Visits 2)

Master H. Hunter

TONNAGE:—

Built at Newcastle

By whom C. S. Swan & Hunter When 1882

NET 1022

Owners Klyde S. S. Co. Limited

Port belonging to London

GROSS 1545

UNDER DECK 124 (if not already recorded in Appendix to Register Book.)

Owners' Address

If Surveyed Afloat or in Dry Dock Afloat Name of Dock Victoria Dock Destined Voyage

Length of Poop ft.: of Forecastle ft.: of Raised Or. Deck ft.: Moulded Depth ft. ins. (if these particulars are not yet recorded in the Register Book.)

Classed

Last Survey, No. 548 Port N. Lk.

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and Initials of any letters respecting this case.)

REPAIRS, OR EXAMINATION AS PER RULE

for damage, striking the Quay entering Victoria Dock Aberdeen.

Fitted bosom piece in a broken frame on port bow, and renewed about 50 feet of batten and space ceiling. This vessel was not due for any survey and was not examined.

PRESENT CONDITION OF THE

Decks	Plank (Bottom) & Counter	Ceiling	Boats
Waterways	Treenails or Rivets	Rudder	Masts, Yards, &c.
Comings	Breasthooks & Stemson	Copper, or Y.M. When put on (State if on Felt.)	Condition, how ascertained
Up'r Dk. Beams & Fastenings	Transoms, Pointers, & Crutches	Cement (if Iron Ship)	Sails
Low'r Dk. Beams & Fastenings	Timbers of Frame at the openings	Caulking of Bot'm, D'k, & Wat'rways	Anchors No. of
Planksheers	Ditto ditto at other places	Windlass & Capstan	Cables
Sheerstrakes	Keelsons	Pumps	Hawsers & Warps
Top-sides	Clamps & Shelves		Standing & Running Rigging
Wales			
Engine Room Skylights	Coal Bunker, Openings, Lids, &c.	Scuppers	Cargo & Main Hatchways
			Hatches

General Observations, Opinion as to Class, &c.:

This vessel struck the Quay entering the harbour of Aberdeen one frame was broken, a bosom piece has been fitted on the broken frame, and the batten and space ceiling has been repaired and damage has been efficiently repaired.

Entry or Registration Fee (if chargeable) (per Section 27, Scale I. or II.)	£ - - -
Survey Fee (per Section 28)	£ - - -
Special Damage Fee (if any) (per Sec. 28)	£ 2 2 0
Certificate (if required)	£ - - -
Travelling Expenses (if chargeable)	£ - - -
Second Surveyor's Fee (if any)	£ - - -

received by me, J. W. Kettle 14 Oct 1884

Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute Friday 17th Oct 1884

acter assigned as now