

3621

Report of Survey for Repairs, &c., of Engines & Boilers.

No. 3621

(Received at London Office,

THURS 12 NOV 1885)

No. in Reg. Book. 54 Survey held at Aberdeen Date, first Survey L Last Survey 22nd Oct 1885
on the Machinery of the S. S. "Saint Clair" (Number of Visits 1)
Tonnage, Gross 59.3 Built at Glasgow When built 1868-2
Ditto, Net 32.6 Owners North of Scotland & S. S. Nav. Co. Port belonging to Aberdeen
Diameter of Cylinder 38 1/4 x 46 1/4 Engines made by Randolph Elder & Co. When made 1868
Length of Stroke 33" Boilers made by V When made 1885
Pressure of Steam 40 lbs If Surveyed Afloat or in Dry Dock Duthie's Slipway Classed *A 1
Registered Horse Power 180 (State name of Dock.)
Last Survey No. Port NB-85 LMC. 2-85

Particulars of Repairs and Examination Broken Stern post
(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from repairs due to other causes. State also the dates and initials of any letters respecting this case.)
The Sea cocks & connections examined & found in good order.
The Tail shaft & stern tube examined & found satisfactory.

It is submitted that this vessel is eligible to remain as classed
M 12/11/85

General Observations, Opinion, and Recommendation :—
(State clearly what alteration, if any, is suggested to be made in the existing notification of the vessel's machinery in the Register Book, consequent upon this survey.)
The machinery of this vessel as far as seen is in good order & eligible in my opinion to remain as classed.

Fee or Registration Fee (per Sec. 27)	12	:	:	received by me, 188
Survey Fee (per Section 28)	2	:	:	
Special Damage Fee (per Section 28)	2	:	:	
Certificate (if required)	2	:	:	
Travelling Expenses (if chargeable)	2	:	:	

Committee's Minute
Assigned

John H. Heck
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.