

Glasgow Report A 4294

LLOYD'S REGISTER OF BRITISH AND FOREIGN SHIPPING

(Received in London Office)



No. 2569

TESTS OF BOILER STEEL.

Tests of 1 Steel plate manufactured by *The Steel Works of Scotland of Blocharin Glasgow* for Boiler No. *102* to be constructed by *J. J. Thompson* of *Glasgow* for _____

Date first visit _____ last visit _____ No. of Visits _____

The *1 plate* specified in the accompanying copy of Advice Notes were rolled from _____ charges. The tensile test has been applied to *1* samples as set forth below, and the temper and bending tests *As required by circular No 438*

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

No.	Purpose.	Charge Mark.	No. of plates or bars in same charge	Mark on plate and test piece.	Dimensions.			Ultimate Stress.		Exten. in 8 ins. %	Remarks.
					Thickn.	Brdth.	Area.	Total.	Sq. Inch.		
					Ins.	Ins.	Ins.	Tons.	Tons.		
<i>1</i>	<i>11 6 1/2 x 5 1/4 x 1/2</i>	<i>9331</i>		<i>4961</i>	<i>.5</i>	<i>1 13</i>	<i>565</i>	<i>15.15</i>	<i>27.0</i>	<i>25.5</i>	

Fee £ : :
 Expenses £ : :
 £ : :

To be paid by *The Steel Works*

J. H. Sandy
 Surveyor, Lloyd's Register,

© 2019 Lloyd's Register Foundation

D. J. 6/5/85