

(Received in London Office)



Tests of 2 Steel pl. manufactured by The Steel Co Scotland of Blochair
for Boiler No. 122 to be constructed by J & J. Thomson of Glasgow
for workman Clark no 45

Date first visit *last visit* *No. of visits*

The _____ specified in the accompanying copy of Advice Notes were rolled from _____ charges. The tensile test has been applied to _____ / samples as set forth below, and the temper and bending tests *satisfactory*

When a second test is applied, the result should be recorded immediately below the record of the original test. The number of plates or bars included in a rejection must be clearly stated.

[illegible]

Fee £ : :

Expenses £ : :

£ : :

To be paid by

John Sanderson

Surveyor, Lloyd's Register,

Glasgow

7/1/84

BELSH-0062