

REPORT of SURVEY for REPAIRS, &c.

3622

Date of Writing Report

October 5th 1889

Port of Belfast

Received in London Office,

MON 7

OCT 1889

in Book.

Survey held at

Belfast

Date, First Survey

and Last Survey

Oct 4th 1889

on the

New Screw Steamer Yorkshire

(No. of Visits)

one

Master - Henry. 89 - 89

YEAR.

MONTH.

TONNAGE:-

ET 2504

ROSS 3871

UNDER DK. 3804

Built at Belfast

By whom

Harland & Wolff Ltd

When 1889 - 7

Owners Bibby Bros. & Co.

Port belonging to Liverpool

Owner's Address

(if not already recorded in Appendix to Register Book.)

Surveyed Afloat or in Dry Dock

Afloat

Name of Dock

Harbour

Destined Voyage

New York

Length of Poop

ft.: of Forecastle

ft.: of Raised Or. Deck

ft.: Moulded Depth

ft. ins.

(if these particulars are not yet recorded in the Register Book.)

To be Classed

Years assigned, if a Wood Ship.

Character in Register Book.

100 A 1

Last Survey, No.

Port

State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Society's Freeboard (if assigned) as painted on Ship

in Summer

7 ft. 5 ins.

in Winter

7 ft. 10 ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR

Freeboard

The Freeboard assigned by the Committee. per Secretary's letter dated as above, has been marked on the vessel's sides in accordance with the requirements of the Rules - as follows. -

In Winter

7 ft. 10 ins.

In Summer

7 ft. 5 ins.

Height of Fresh water line above Centre of Disc

6

PRESENT CONDITION OF THE

Boats

Masts, Yards, &c.

Condition, how ascertained

Sails

Anchors No. of

Cables

Hawsers & Warps

Standing & Running Rigging

Hatches

Plank (Bottom) & Counter

Treenails or Rivets

Breasthooks and Stemson

Transoms, Pointers, & Crutches

Timbers of Frame at the opening

Ditto ditto at other places

Keelsons

Clamps & Shelves

Ceiling

Rudder

Windlass & Capstan

Pumps

Cement (if Iron Ship)

Caulking of Bot'm, D'k, & Watrways

Copper, or Y.M.

(State if on Felt.)

When put on

Scuppers

Cargo & Main Hatchways

Room Skylights

Coal Bunker, Openings, Lids, &c.

General Observations, Opinion as to Class, Recommendation, &c.:

The Freeboard having been marked on the vessel's sides, as shown in Notice No. 542, it is recommended that a record thereof be made in the Register Book.

This Report accompanies the First Entry Report.

Fee (if chargeable) per Scale I., Sec. 27...

Fee (if chargeable) per Scale II., Sec. 27...

Fee (per Section 28)

on Damage, Fee (if any) (per Sec. 28)

ificate (if required) to be sent as per margin

ling Expenses (if chargeable)

Surveyor's Fee (if any)

Committee's Minute

Character assigned

Fees applied for,

18


Received by me,

18

James Curpin

Surveyor to Lloyd's Register of British & Foreign Shipping.

Record Freeboard



Lloyd's Register Foundation