



Belfast.

8th Sept. 1890

Dear Mr. Johnston,

Just
for your wire re Marley's
and have 3 minutes to
Reply.

The thickness of side
plating from upper turn
of bilge to sheerstrake
is $\frac{8 \text{ to } 7}{20}$.

Yours faithfully.
James Maxton

W. Johnston Esq.

BEL57-0162